


TERRA CONTRACTING INC.

FlexKrete

FIRE HYDRANT VALVE COLLAR REPAIR

This concrete collar was damaged due to heavy delivery truck traffic. The smaller cracks were ground out and enlarged with a 4" grinder and a metal grinding wheel. A thin coating of primer was applied and followed by the application of a 3:1 (3 sand 1 FlexKrete) mixture of FlexKrete. The mix was troweled into the cracks as well as across the concrete collar.



Once the FlexKrete hardened a final brushing and a light broadcast of black aggregate was applied.

