



FlexKrete

PATCH ON "ALLIGATORED" ASPHALT

This patch was a test on a deteriorating asphalt parking lot at the Merced County Airport in Merced CA. The purpose of the test was to determine if FlexKrete could be used to repair such severely damaged asphalt. The patch was placed 11-30-2013 and the picture was taken 1-18-2014, 50 days later. Traffic in the parking lot consists of normal commuter vehicles as well as daily tour buses.

